


Wayne W. Rupert Klarquist Sparkman, LLP Narquist Sparkman, LLP 121 SW Salmon Street, Suite 1600 Portland, Oregon 97204 Telephone: (503) 226-7391 Notice of Allowance: June 18, 2003 Application No.: 09/971,952 Our Ref. No. 6047-61248
First Named Inventor: Casey Prindiville et al.
For: SEMICONDUCTOR PACKAGE HAVING
DEFECTIVE SUBSTRATE


ne 18, 2003 Confirmation No. 4096 1,952 Filed: October 4, 2001 Replacement Sheet (Sheet 1 of 5)

38 10 16 26 22 24 FIG. 1A (PRIOR ART)



Wayne W. Rupert
Klarquist Sparkman, LLP
121 SW Salmon Street, Suite 1600
Portland, Oregon 97204
Telephone: (503) 226-7391
Notice of Allowance: June 18, 2003
Application No.: 09/971,952
Replacement Sheet (Sheet 2 of 5)

Our Ref. No. 6047-61248
First Named Inventor: Casey Prindiville et al.
For: SEMICONDUCTOR PACKAGE HAVING DEFECTIVE SUBSTRATE





Wayne W. Rupert Klarquist Sparkman, LLP 121 SW Salmon Street, Suite 1600 Portland, Oregon 97204

Portland, Oregon 97204


Telephone: (503) 226-7391

Notice of Allowance: June 18, 2003

Application No.: 09/971,952

Replacement Sheet (Sheet 3 of 5)

Our Ref. No. 6047-61248 First Named Inventor: Casey Prindiville et al.
For: SEMICONDUCTOR PACKAGE HAVING
DEFECTIVE SUBSTRATE






Wayne W. Rupert Klarquist Sparkman, LLP 121 SW Salmon Street, Suite 1600 Portland, Oregon 97204 Telephone: (503) 226-7391 Notice of Allowance: June 18, 2003 Application No.: 09/971,952

Our Ref. No. 6047-61248 First Named Inventor: Casey Prindiville et al. For: SEMICONDUCTOR PACKAGE HAVING DEFECTIVE SUBSTRATE

ne 18, 2003 Confirmation No. 4096 ,952 Filed: October 4, 2001 Replacement Sheet (Sheet 4 of 5)






FIG. 3B



Wayne W. Rupert Klarquist Sparkman, LLP 121 SW Salmon Street, Suite 1600 Portland, Oregon 97204 Telephone: (503) 226-7391 Notice of Allowance: June 18, 2003 Application No.: 09/971,952

Our Ref. No. 6047-61248
First Named Inventor: Casey Prindiville et al.
For: SEMICONDUCTOR PACKAGE HAVING
DEFECTIVE SUBSTRATE

ne 18, 2003 Confirmation No. 4096 952 Filed: October 4, 2001 Replacement Sheet (Sheet 5 of 5)

